



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program February 20, 2013

Reviewed: 

<b>Mine Name :</b> Carr Fork – Pine Canyon	<b>Permit Number:</b> M/045/0004
<b>Operator Name:</b> Kennecott Utah Copper	<b>Inspection Date:</b> March 10, 2011
<b>Inspector(s):</b> L Heppler, Peter Brinton	<b>Time:</b> 3:00 pm
<b>Other Participants:</b> Zeb Kenyon - Kennecott	<b>Mine Status:</b> Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>


**Bond Renewal Date:** 12-01-2016 **Bond Amount:** \$134,905 **Permit fee** is up to date

**Purpose of Inspection:** Routine annual inspection. This site was inspected as a Large mine site on 12/02/2009.

**Inspection Summary:** Mine site had a locked gate on the entrance road, both shaft and portal were secured. No erosional problems were noted. Most of ground disturbance has been reclaimed, including both regrading and revegetation. Revegetation is successful, dominately grasses but also includes biodiversity and locally established conifers. Attached photograph document remaining structures

Photos were taken to document site conditions.

**Conclusions and Recommendations:** OGM to continue annual inspections and monitor the site when in the area.

**Inspector's Signature** 

LAH:eb

cc: Kennecott – Kelley Payne

O:\M045-Tooele\M0450004-PineCanyonMine\inspections\Insp-03102011.doc





Gate



Head frame for shaft



Overview of the warehouse



Close up of warehouse